DPD-2516-59 Copy Cort

14 April 59

MEMORARDUM FOR: Chief, Administrative Branch, DFD

SUBJECT : Water Coolers, IPD Area

- 1. A survey of possibilities to provide drinking water facilities as suggested in your memorandum dated 8 April 1959 has been completed. It is not feasible to install a water fountain in any location on the fifth floor other than one just inside the barrier on the north east corner. The other location, inside the barrier on the south west side of the building (administrative area), necessitates major modifications to the building which the owner will not condone.
- 2. Security does not concur in bottled water due to procedures involved in replemishment procedures within the secured area.
- 3. A request to install the one water fountain in the north east side of the fifth floor was initiated on 9 April 1959. This will negate the necessity to pass two guard posts.

Dist:

0 & 1 - addee

cc - Mat, cy 3

- RI, cy 4

25X1A

Chief, Hateriel Branch
DFD-DD/P